## Material Safety Data Sheet

HFRP HMIS Codes: 1\* 0 0 B

Brand Name: Conco. Pro Product Number: 1600 White

Product Description: Exterior Acrylic Flat House Paint

--- Section I - Manufacturer Identification -----

Manufacturer's Name: Conco Paint Company

Address: 12234 Los Nietos Rd., Santa Fe Springs, CA 90670 Emergency Phone: (800) 486-7889 Information: (800) 486-7889

Date Revised: 10-15-98

#### HAZARDOUS INGREDIENTS/SARA III INFORMATION SECTION II -

	· · · · · · · · · · · · · · · · · · ·		
CAS MUNDER			WEIGHT PERCENT
107-21-1	.06	77 P	2.1
<sup>*</sup> 1897 <b>-45-6</b>	N/A	N/A	0.28
ents of California Propo	sition 65	Safe Drinki	ng Water and Toxic
•			• •
	•	-	
,		3,	
based paints.			
AND EXPLOSION	I HAZAR	D DATA	
•			
METHOD USED:	• TCC		
•	107-21-1 1897-45-6 ents of section 313 of 9 ents of California Property CAL/CHEMICAL C SPECIFIC GRAEVAPORATION MATERIAL V.C based paints.	107-21-1 .06  1897-45-6 H/A  ents of section 313 of Title III a ents of California Proposition 65  CAL/CHEMICAL CHARACT  SPECIFIC GRAVITY ( EVAPORATION RATE: MATERIAL V.O.C.: based paints.	107-21-1 .06 77 F  1897-45-6 N/A N/A  ents of section 313 of Title III and of 40 CF ents of California Proposition 65 Safe Drinki  CAL/CHEMICAL CHARACTERISTIC  SPECIFIC GRAVITY (H2O=1): EVAPORATION RATE: Slower MATERIAL V.O.C.: 42 g/1

EXTINGUISHING MEDIA: Foam, CO2, Dry Chemical, or Water Fog.

SPECIAL FIREFIGHTING PROCEDURES Cool containers with water spray.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containter exposed to high temperatures may explode or burst due to build up of steam pressure.

SECTION V REACTIVITY DATA

STABILITY: Stable. CONDITIONS TO AVOID

INCOMPATIBILITY (MATERIALS TO AVOID)

Avoid contact with strong oxidizing agents.

# MATERIAL SAFETY DATA SHEET

1601P-01

Page: FLAT HOUSE PAINT - HI HIDE WHI TE

2

### ARDOUS DECOMPOSITION OR BYPRODUCTS

May form toxic materials; Carbon Dioxide, Carbon Monoxide, Various Hydrocarbons, etc. on thermal decomposition.

HAZARDOUS POLYMERIZATION: Will not occur.

SECTION VI - HEALTH HAZARD DATA ==

## INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Adverse health effects from vapors or spray mists in poorly ventilated areas may include irritation of the nucous membranes of the nose, throat, and respiratory tract and symptoms of headache and nausea.

#### SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

EYES: In direct contact, may cause irritation. SKIM: Prolonged and repeated contact with product may cause skin irritation.

## SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Redness, drying of the skin, or other signs of irritation or contact dermititus.

## INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Can cause gastrointestinal irritation, nausea, vomiting, and diarrhea.

## HEALTH HAZARDS (ACUTE AND CHRONIC)

ACUTE: May cause irritation to skin and eyes, gastrointestinal irritation, nausea, and vomiting. CHRONIC: Prolonged or repeated exposured above TLV may result in permanent brain and nervous system damage. CHRONIC: Prolonged or repeated exposure to this product may cause cancer.

IARC MONOGRAPHS: Yes OSHA REGULATED: No CINOGENICITY: NTP CARCINOGEN: No Wanning! This product contains chemical(s) known to the State of California to cause cancer. (California Health and Safety Code Section 25249.5) (Prop. 65). WARNING! This product contains chemical(s) known to the State of California to cause birth defects or other reproductive harm. (California Health and Safety Code Section 25249.5) (Prop. 65).

## MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

May be aggravating to some skin and respiratory conditions, and to pre-existing liver and/or kidney disorders.

## EMERGENCY AND FIRST AID PROCEDURES

EYES: Flush with large amounts of water for at least 15 Nimutes. Take to a physician.

SKIN: Wash affected areas with soap and water. Remove contaminated clothing. If irritation persists, consult physician.

INHALATION: Remove to fresh air. Treat symptomatically. Consult physician.

INGESTION: Drink 1 or 2 glasses of water to dilute. DO NOT INDUCE VONITIN G. CONSULT A PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY. TREAT SYMPTOMATICALLY.

## SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

## STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Dike, contain, or absorb with inert materials. Transfer to containers for recovery or disposal. Prevent runoff into sewers, streams, or other bodies of water.

#### WASTE DISPOSAL METHOD

Dispose of in accordance with all local, state and federal regulations.

## PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Do-not expose to extremes in temperature. Avoid exposure to high temperatures. DO NOT ALLOW TO FREEZE.

## OTHER PRECAUTIONS

DO NOT TAKE INTERNALLY. Avoid prolonged or repeated exposure to levels above TLV. KEEP OUT OF REACH OF CHILDREN.

MATERIAL SAFETY DATA FLAT HOUSE PAINT - HI HIDE WHI TE

1601P-01

SECTION VIII -CONTROL MEASURES

Page:

#### RESPIRATORY PROTECTION

Not normally required. If TLV is exceeded, use NIOSE/MSEA approved organic vapor and mist, supplied air, or self-contained breathing apparatus. Avoid breathing sanding dust.

## **VENTILATION**

Use adequate mechanical (general and/or local) ventilation to maintain exposure below TLV.

#### PROTECTIVE GLOVES

Wear resistant gloves such as polyethylene.

#### EYE PROTECTION

Use chemical spalsh goggles or OSHA permitted safety glasses.

#### OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Wear impervious clothing. Eyewash station.

## WORK/HYGIENIC PRACTICES

Wash bands before eating or using restrooms. Remove and wash all contaminated clothing before reuse.

SECTION IX -DISCLAIMER

The information contained herein is furnished without warranty of any kind. Employers should use this information only as a supplement to other information gathered by them and must make independent determination of suitability and completeness of information from all sources to assure proper use of these materials and the safety and health of employees.